
#### भारत सरकार/ Government of India

## पर्यावरण, वन और जलवायु परिवर्तन मंत्रालय/ Ministry of Environment, Forest & Climate Change

# पूर्वी क्षेत्रीय कार्यालय/ Eastern Regional Office





Ph: 0674-2301213, 2301248, 2302452, 2302453, Fax: 2302432, E mail: roez.bsr-mef@nic.in

संख्या 101-260/ई.पी.ई

स्पीड पोस्ट

09-02-2018

सेवा में,

उप महाप्रबंधक, इंडियन ऑइल कारपोरेशन लिमिटेड (रिफाइनरी), पारादीप रिफाइनरी प्रोजेक्ट, पोस्ट ऑफिस : झिमानी, कुजंग, जगतसिंहपुर -754 141 ओडिशा

विषय : इंडियन ऑइल कारपोरेशन लिमिटेड (रिफाइनरी),परियोजना के अनुपालन की प्रमाणित पत्र के संबंध में |

महोदय,

मुझे यह सूचित करने का निर्देश हुआ है कि इस कार्यालय द्वारा दिनांक 27.04.2017 एवं 05.02.2018 को उपोरोक्त परियोजना की मोनीटरिंग की गई | इस सन्दर्भ में अनुपालन की प्रमाणित पत्र आप के आवश्यक कारवाई हेतु संग्लग्न हैं |

संग्लनकः यथोक्त

भवदीय,

(डॉ. ए. के. गुप्ता)

संयुक्त निदेशक (वै)




#### भारत सरकार/ Government of India

### पर्यावरण, वन और जलवायु परिवर्तन मंत्रालय/ Ministry of Environment, Forest & Climate Change पूर्वी क्षेत्रीय कार्यालय/ Eastern Regional Office

## ए/3 चन्द्रशेखरपुर/A/3 Chandrasekharpur,





No.101-260/EPE

09-02-2018

To

The DGM-HSE, Indian Oil Corporation Ltd.(Refineries Division), Paradip Refinery Project, PO: Jhimani, Via: Kujang, Dist: Jagatsinghpur, Odisha -754 141

Sub:

Issue of Certified Compliance report in respect of 15 MTPA refinery along with SPM-II of Paradip Refinery project (formerly known as eastern India refinery project of 9 MMTPA capacity) located at village Abhaychandrapur, Jagatsinghpur, Orissa by M/s Indian Oil Corporation Ltd(IOCL)-reg.

Ref: Ministry's EC No. EC No. J-11011/70/2007-1A II (I) dated July 6, 2007.

The projected was monitored by the undersigned 27.04.2017. The project officials like, Shri TDVS Gopalakrishna, Chief General Manager (TS), Dr. Ashutosh Mishra, Senior Quality Control Manager, Shri Sarvesh Kumar, Dy. General Manager (Quality Control), Shri B.K. Das, DGM (H, S & E) were present during monitoring.

The project was accorded ToR for installation facilities of BS VI MS/HSD (ISOM-1100 ton MTPA IMDMADGDX-1150 ton MTPA HGU-2 X 60 ton MTPA kero HDS-300 ton MTPA DHDT) vide letter No.J-11011/344/2016-IA II (I) dated 28.02.2017 for installation of ethylene recovery unit (ERU) and mono ethylene glycol unit (MEG). The Ministry had made amendment in the ToR vide letter No.J-11011/344/2016-IA.II (I) dated 30<sup>th</sup> May, 2017.

The PAs have complied or are in process of complying with the conditions stipulated by the Ministry. In this context, information/action plans have been sought on following points:

- i. It is required to submit quantum of effluent treated on daily basis, recycled and discharged to sea. It is also requested to submit inlet and out let quality analysis of effluent to this office. It has been noticed that PAs are using ETP outlet water for the purpose of gardening, which is contradictory to the above condition. Therefore, it is directed not to use ETP outlet waste water for the purpose of gardening. During monitoring it has been noticed that the RO system of the ETP is not functioning,
- ii. It is required to conduct marine water quality analysis on regular basis and report should be submitted before Regional Office,
- iii. It is required to increase green belt with indigenous variety of plant species which are showing (1791) resistance towards SOx emission within the plant area i.e. 2951 acre excluding township area. (ATRUE) It is advisable not to plant fruit bearing plants in project site,

NOTOS INC. 1910 No information has been submitted on the Oil Spill Contingency Plan and Marine Disaster of value and Management Plan. It is required to submit the plans at the earliest.

njuri, kā **r¥/Ea**kšem Bojuno ki kmigg**ay Bhuba**noswen¥51025

(डा. ए. के. गुप्ता)
(DR. A. K?अडाअनिक)
संयुक्त निदेशक/JOINT DIRECTOR
भारत सरकार/Govt. of India
सर्वाय ज.प. मंत्रालय/Min. of Env. Fore
सेत्रीय कार्यालय/ Eastern Regional (अम्बनेश्वर/Bhubaneswar-751023

Ministry's EC No. J-11011/70/2007-1A II (I) dated July 6, 2007

. N.	CONDITIONS	Status of	complia	nce			
1	SPECIFIC CONDITIONS:	***************************************					
					- T- 7		, Kaz to
i.	The company shall ensure strict	As stated b	a di Da				
	implementation/ compliance to the stimulation	As stated b	by the PAs	they are	comply	ing wit	h the abo
	I made by MIOEF vide OM No. I-11011/24/1007 va	condition.					
	II dated 24th December, 1997.						
ii.	The garage						-
	The gaseous emissions (SO <sub>2</sub> , NO <sub>x</sub> , CO, NMHC &	Stack emis	sion bein	g monito	red for	adhar	
	Benzene) from the various process units shall	MOEL DOE	lication d	ated 18 <sup>th</sup>	March	2008	It has h
ı	conform to the standards prescribed under the	tound that	PAs hav	e set un	7 nos	of A	mhiane
_	Environment (Protection) Rules, 1986 or norms	Quanty IVI	onitoring	(AAOM	) static	one has	ed on
	stipulated by the SPCB whichever is more	modelinia	exerci	se cor	idiicted	1170	400
	stringent. At no time, the emission level shall go	Comprehen	sive EIA	Study. C	ontinu	Olie ma	nitani
	beyond the stipulated standards. In the event of	an mic \	monito	ring stat	ion h	as alra	adv P
	failure of pollution control system(s) adopted by	mibremente	a whic	h are	conne	cted	sreith i
	the unit, the respective unit should not be	OSPCB/CF	'CB serve	r. The d	ata of a	online i	monitor
İ	restarted until the control measures are rectified to achieve the desired efficiency.	aramon qi 6	iound w	thin the	limit i	n all e	aron ait
	-	submitted o	iata for t	ne month	of Apr	il. 201	7 has ha
		furnished be	low:			,01	, mas De
							•
			SOx (mg/Nm³)	NOx	co	PM <sub>to</sub>	PM <sub>2.5</sub>
			(mg/ tviii )	(mg/Nm	(mg/ (Nm³)	(mg/N m³)	(mg/Nm
	1.		28	20	0	27	<del> </del>
	1		12	8	1	38	15
1			8	11	0	30	17
1	1		17 30	9	1	77	20
	į į		14	15	1 -	56	27
	į		20	$\frac{15}{9}$	7	51 46	30 16
				<del></del>	<u> </u>		
	j	The data of s	tack emis	sion for ti	he mon	th of M	lav. 201
	i	s furnished b	elow:				),01
	\r						_
1.	· · · · · · · · · · · · · · · · · · ·	CDU	70.4	(mg/Nm³)		(mg/Nn	n³)
1	1 ⊨	VDU	91.7		10.18		
1		DCU – 1	49.2		39.6	<u> </u>	
	' I <del> </del>	FCC	42.7		15.6		
	I [-	DHDT	71.4		14.87		
	! <del> </del>	NHDT VCO HDT	25.4		12.2		
1	1 -	VGO-HDT	42.8		20.8		
ľ	t I i	HRSG-3	39.2		20.7		

UB-3

141

128.7

16.87

(डा. ए. के. गुप्ता) (DR. A. K. GUPTA) संयुक्त निदेशक/JOINT DIRECTOR भारत सरकार/Govt. of India र्जिवरण वन एवं ज.प. मंत्रालय/Min. of Env. Fores' र्त्री क्षेत्रीय कार्यालय/Eastern Regional Of भुवनेश्वर/ Bhubaneswar-751023

Ministry EENJ-180)1/70/2007-1A II (I) dated July 6, 2007 (AT GUP) A A AU)

Page 2 of 8

iii. Ambient air monitoring stations, [SPM, SO<sub>2</sub>, NO<sub>x</sub> and NMHC, Benzene] shall be set up in the refinery complex in consultation with SPCB, based on occurrence of maximum ground level concentration and down-wind direction of wind. The monitoring network must be decided based on modelling exercise to represent short term GLCs. Continuous on-line stack monitoring equipment shall be installed for measurement of SO<sub>2</sub> and NO<sub>x</sub>. Data on VOC shall be monitored and submitted to the SPCB/ Ministry.

It has been found that PAs have set up 7 nos. of Ambient Air Quality Monitoring (AAQM) stations based on the modelling exercise conducted under the Comprehensive EIA Study. Continuous monitoring in all the 7 monitoring station has already been implemented which are connected with the OSPCB/CPCB server. The data of online monitoring station are found within the limit in all seven sites. Submitted data for the month of April, 2017 has been furnished below:

Locations	SO	NOx	СО	PM <sub>10</sub>	PM <sub>2.5</sub>
	x				
	(mg/Nm³)		(m	(mg/Nm³)	
AAQM-1	28	20	0	27	
AAQM-2	12	8	1	38	15
AAQM-3	8	11	0	30	17
AAQM-4	17	9	1	77	20
AAQM-5	30	6	1	56	27.
AAQM-6	14	15	7	51	30
AAQM-7	20	9	1	46	16

The data of stack emission for the month of May, 2017 is furnished below:

	SOx (mg/Nm³)	NOx (mg/Nm³)
CDU	70.4	10.18
VDU	91.7	12.78
DCU - 1	49.2	39.6
FCC	42.7	15.6
DHDT	71.4	14.87
NHDT	25.41	12.2
VGO-HDT	42.8	20.8
HRSG-3	39.2	20.7
UB-2	141	16.87
UB-3	128.7	14.7

The total SO<sub>2</sub> emission from the refinery complex shall not exceed 1000 kg/hr after fully stabilizing of the expansion and modernization of the refinery complex and upgrading the existing facilities.SO<sub>2</sub> emission report may be made on daily basis for all the stacks (fuel burning and process emissions through the computerized mechanism). Further, regular monitoring of stacks every fortnight must also be carried out to check the data obtained computerized monitoring by engaging a reputed organization. In addition, a monthly sulphur balance statement indicating type of fluid, its Scontent, product S - content, SO2 emission etc. may be made. Daily, fortnightly and monthly reports generated as above shall be sent to the SPCB and MOEF.

It has been stated that the SO<sub>2</sub> emission from the unit for the year 2016-17 are 6982 MT and SO2 emission from unit fuel firing (considering on-stream hour as 83.20 hrs) is 839.1 MT which is within the limit prescribed above. However, as per stack monitoring data (in house), submitted stack emission data for the period of December, 2016 to March, 2017, the value of SOx and NOx in all stack of boiler and fire heater is found within the prescribed limit.

v. All the Sulphur Recovery Units shall have overall efficiency of 99.9%.

(DÉ A.K GÜPTA) MOZEGERAMUSE CELIC It has been found that PAs have already set up Sulphur Recovery plant with 99.9% efficiency. It is required to conduct its efficiency test on regular basis.

Ministry's EC No. J-11011/70/2007-1A II (I) dated July 6, 2007

An a folklich am om begreite. Gebruik breibensower 181126 Page 3 of श्रीणा (डा. ए. के. गुप्ता) (डा. ए. के. गुप्ता) (DR. A. K. GUPTA) संयुक्त निदेशक/JOINT DIRECTOR भारत सरकार/Govt. of India राण वन एवं ज.ए. पंत्रालय/Min. of Env. Forest क्षेत्रीय कार्यालय/ Eastern Regional Offi

Г	vi.	YYlaw Y	
	V1.	The state of the s	ie It has been found that BA a hours
		and a void excessive formation	of lt has been found that PAs have set up Ultra Low le burners in major fired heaters.
		NO <sub>x</sub> .	- more in major filed fleaters.
	vii.	Company shall :	
		Company shall install online SO <sub>2</sub> and NO	Ox It has been found that PAs have set up on-line SO <sub>2</sub> and
-		analysers in all the stacks of the refinery.	NO <sub>x</sub> analyser devices in all the stacks of the refinery.
v	iii.	Fugitive emission 6 TXS 6	x many ser devices in an the stacks of the refinery.
		Fugitive emissions of HC from product storag	e It has been found that PAs are conducting (in house)
		I was talled the mist be recordable as a con-	a c conducting (in house)
-		defecting HC leakage shall t	but analysis report has not been submitted to this
1		Provided at Strategic locations No.	_ supmitted to this
		measures shall be adopted so as to ongue at	addition to above, PAs have
		The rest of the reference to	To leakage on the tankage
		Promises do not exceed prescribed limit	<u> </u>
		1 " A Controlled data Shall be submitted to Open	. 1
		to be every three months and to Minister	r l
1		Environment & Forests every six months.	
<del>  .</del>	 ĸ.		
"	٠.	For control of fugitive emissions, the company	It has been found that DA. !
.]		auginelli rollte all	I we taken various satemand
		nydrocarbons to the flare system in addition	The same of the sa
		The straig have system. All the many	are using flare system for
		outer equipment where there is a likelike at a	Tydrocarbon before -1.
	- 1	rearages shall be provided	The stated earlier. PAs have been full
	- [	midicators and also provide for immediate	LDAR system in tankage area.
		Station of Such Edulpment in case of - 1 - 1	
	- 1	The company shall adopt Leak Details	
	- 1	Pull (LDAN) programme for quantities!	
	- 1	and control of fugitive emissions.	
x.		All the stacks shall be of appropriate design and	As stated all the
	- 1	morgan shall be attached to pollution and a	As stated, all the major stack height are more than 60
	- 1	Jacoms, wherever necessary All starter in	and height of flare is 131 m which is as now 41.
	- 1	complex must meet the minimum start 1	design mentioned in the EIA report.
	- 1 '	orrectia as prescribed in the Envisorment	
		Protection emissions.	
<del>.</del>	ļ		
xi.		All new standards/ norms which are being	They have
	[	oposed by CPCB for refinent product in	They have assured to comply with the condition.
		Detrochemical units shall be applicable for a	
	1 1	roposed expansion and modernization at a l	
		relinery compley The	
	S	tandards shall be incorporated into the detail	1
	-	coigns for the proposed exposure 1	
	**	iodermzation. The existing refiners commit	
	sl	hall also be upgraded to the new above	
	m	entioned emission standards.	·
	┞_		
ii.		round water shall not be tapped for I	
	co	Instruction, industrial	t has been stated that PAs are not drawing ground
	in	cluding the township.	rates for construction work including the township
		a	rea.
			<del>/</del>

Jomes

(डा. ए. के. गुप्ता)
(DR. A. K. GUPTA)
संयुक्त निदेशक/JOINT DIRECTOR
भारत सरकार/Goyt, of India
ध<sup>्रा</sup>ित्रण वन एवं ज. प. मंत्रालय/Min. of Env. Forest
ूर्ग क्षेत्रीय कार्यालय/ Eastern Regional Off.
भुवनेश्वर/ Bhubaneswar-751023

Ministry's EC No.J-11011/70/2007-1A II (I) dated July 6, 2007

(BLU B. 1991)

(DR. A. K. GURTA)

(DR. A. K. GURTA)

(DR. A. TEANDAL FORWARD

(DR. TEANDAL

(DR. TEAND

xiii.	Liquid effluents shall be treated to conform to the standards stipulated by CPCB / Ministry of Environment & Forests under EPA 1986 and also the new norms being specified. Treated effluent will be recycled and reused. The treated effluent shall be discharged into the sea through a pipeline of about 3 km from low tide line. The domestic effluent after treatment and conforming to the prescribed standards shall be used for greenbelt development.	It has been stated that PAs have set up effluent treatment plant for treatment of industrial treatment and sewage treatment plant for domestic effluent treatment. The treated water is reused up to certain extent and remaining water is being discharged to the sea through a pipeline of about 3 km from low tide line. It is required to submit quantum of effluent treated on daily basis, recycled and discharged to sea. It is also requested to submit inlet and out let quality analysis of effluent to this office. It has been noticed that PAs are using ETP outlet water for the purpose of gardening, which is contradictory to the above condition. Therefore, it is directed not to use ETP outlet waste water for the purpose of gardening. During monitoring it has been noticed that the RO system of the ETP is not functioning.
xiv.	The company shall undertake monitoring of the groundwater quality at the locations as suggested by the Central Ground Water Board. Monitoring results of the same shall be submitted to the OPCB/CPCB and MOEF.	It has been found that PAs are conducting ground water analysis in ETP area. As per the submitted in house (NABL accredited laboratory) monitoring report, values are found within the limit.
xv.	M/s IOCL shall undertake rainwater harvesting measures to recharge the ground water in the area in consultation with Central Ground Water Board and Orissa Pollution Control Board.	It has been found that PAs have set up two storm water reservoirs (Capacities: 2,96,000 KL and 3,13,000 KL) to store rain water in monsoon in the refinery premises.
xvi.	Green belt shall be raised in 580 acre area as per CPCB guidelines.	As stated, PAs have developed in an area of 580 acres with the help' of Orissa Forest Development Corporation Ltd. (OFDCL). 5,87000 trees have been planted around the refinery area and approx. 50682 trees have been planted in the township. Every year also, Paradip Refinery is doing plantation in and around Refinery. Till date approximately 7.4 lacs trees have been planted. However, it is required to increase green belt with indigenous variety of plant species which are showing resistance towards SOx emission within the plant area i.e. 2951 acre excluding township area. It is advisable not to plant fruit bearing plants in project site.
xvii.	Occupational Health Surveillance of the employees and workers shall be done on a regular basis and records maintained as per the Factories Act.	It has been stated that PAs are conducting occupational health surveillance of the employees and workers and records are being maintained.
xviii.	The marine water quality shall be regularly monitored for the water quality (temperature, petroleum hydrocarbons, phenols, sulphides, total organic carbon), sediment quality (trace elements, petroleum hydrocarbons, TOC and sediment size) and biological parameters (primary productivity, benthos, fish quality and growth, biomass, phytoplankton and zooplankton).	It has been found that M/s PDIL, third party has been engaged for conducting the marine water quality monitoring. The report is yet to be submitted. During monitoring it has been noticed that PAs are not conducting biological parameters (primary productivity, benthos, fish quality and growth, biomass, phytoplankton and zooplankton) by the third party. It is directed to conduct marine water quality analysis on regular basis and report should be submitted before Regional Office.
xix.	The design, material of construction, assembly, inspection, testing and safety aspects of	It has been stated that the PAs are following the

Ministry's EGNort-11011/70/2007-1A II (I) dated July 6, 2007

[9] A S1(1)

[9] A S1

Page 5 of 8 (डा. ए. के गुप्ता)
(BR. A. Ky GUPTA)
संयुक्त निदेशक/JOINT DIRECTOR
भारत सरकार/ Govt. of India
पर्यावरण वन एवं ज.प. मंत्रालय/Min. of Env. Fo

_		
	operation and maintenance of pipeline a transporting the oil shall be governed ASME/ANSI B31.8/B31.4 and OISD standard 14	her
x	x. The project authorities should install SCAL	24 1.1
	system with dedicated optical fibre bas telecommunication link for safe operation pipeline and Leak Detection System. Intellige pigging facility should be provided for the entipipeline system for internal corrosismonitoring. Coating and impressed curre cathodic protection system should be provide to prevent external corrosion.	pipeline is through Optical file cable and is installed South Oil jetty pipelines.
xxi	project authorities shall natrol and income	ct As stated by the project proponent that cathodi
	per OISD guidelines and continuous monitoring of pipeline operation by adopting nor destructive method(s) of testing as envisaged if the EMP. Pearson survey and continuous potential survey should be carried out at regular intervals to ensure the adequacy of cathods.	protection for underground piping under commissioning.
<u></u>	protection system.	
xxii.	The solid waste shall be disposed off in secured landfill facility within the refinery. The spen catalyst and incinerated sludge will be stored in segregated manner in the secured landfill area Tank bottom sludge from refinery operation shall be put to oil recovery system and the residual sludge will be incinerated. The incinerated sludge ash shall be stored in secured landfill inside refinery. Bio sludge shall be stored in drying pit for natural weathering and then used as manure inside refinery premises.	disposed to secured land fill area which is very poorly managed by IOCL. However, they are in process to commission incinerator per 100 kg/hr. They are having two oil sludge drying pit and one bio sludge drying pit. Therefore, it is directed to submit time bound plan for commissioning of the incinerator and also management of secured land area to the Regional Office.
XIII.	The company shall also comply with all the conditions and safeguards prescribed in the EIA & Risk Assessment Reports.	It has been found that PAs are complying or in process to comply with the safeguards prescribed in the EIA and Risk Assessment reports.
xiv.	The On-site and Off-site Emergency Preparedness Plans, Oil Spill Contingency Plans, Marine Disaster Management Plan shall be prepared for the enhanced refinery throughput and submitted to the Ministry before commissioning at the enhanced capacity.	It has been found that on-site and off-site preparedness plan is in place. It was also stated that Emergency Response and Disaster management Plan (ERDMP) has been approved by MoP&G. On-site emergency plan is approved by Director of Factories and Boiler. Off-site plan has been incorporated in District Emergency Plan. No information has been submitted on the Oil Spill Contingency Plan and Marine Disaster Management Plan. It is required to submit the plans at the earliest.
	The Environment Management Cell and laboratory facilities for the collection of the samples shall be augmented with suitable facilities and qualified personnel and directly report to the chief executive of the refinery complex.	It has been found that Environment Management Cell has been formed headed by GM-HSE. IOCL has NABL accredited laboratory which is handled by SGS officials. It is required to provide training to Environmental Management officials on the biological parameter of water and toxicity assessment for better understanding and compliance of
inistry'	s EC No.J-11011/70/2007-1A II (I) dated July 6, 2007	Air

Ministry's EC No.J-11011/70/2007-1A II (I) dated July 6, 2007

(श. ए. के. पृष्टा (श. ए. के. पृष्टा व्यापन के स्वरूपकी क्षण करणे ज्या के स्वरूपकी क्षण करणे अस्य सम्बंधिया रहे स्वरूपकी (डा. प्र.के. Pageff of 8 (DR. A. K. GUPTA) संयुक्त निदेशक/JDINT DIRECTO भारत सरकार/Govt. of India गर्यांक्रण वन एवं ज.प. मंत्रालय/Min. of Env. Fo ्रार्वी क्षेत्रीय कार्यालय/Eastern Regional भवनेश्वर/Bhuhaneswar/761000

		the stipulated condition.
xxvi.	The company shall prepare comprehensive EIA/EMP report and submit to the Ministry within one year.	It has been found that comprehensive EIA Report has been prepared and submitted.
В.	GENERAL CONDITIONS:	
i.	The project authorities must strictly adhere to the stipulations made by the Orissa State Pollution Control Board and the State Government.	The Consent Order for discharge of sewage and trade effluent has been obtained from SPCB, Odisha vide Order No.5527/IND-I-CON-6414 dated 18.04.2017 which is valid up to 31.03.2018.
ii.	No further expansion or modernization in the plant shall be carried out without prior approval of the Ministry of Environment and Forests.	The project was accorded ToR for installation facilities of BS VI MS/HSD (ISOM-1100 ton MTPA IMDMADGDX-1150 ton MTPA HGU-2 X 60 ton MTPA kero HDS-300 ton MTPA DHDT) vide letter No.J-11011/344/2016-IA II (I) dated 28.02.2017 for installation of ethylene recovery unit (ERU) and mono ethylene glycol unit (MEG).
iii.	At no time, the emissions shall go beyond the prescribed standards. In the event of failure of any pollution control system adopted by the units, the respective unit should be immediately put out of operation and shall not be restarted until the desired efficiency has been achieved.	It has been found that PAs have installed pollution control system in case of increase of pollution load beyond the prescribed limit; the unit shall automatically be switched off.
iv.	The overall noise levels in and around the plant area should be kept well within the standards (75 dBA) by providing noise control measures including acoustic hoods, silencers, enclosures etc. on all sources of noise generation. The ambient noise levels should conform to the standards prescribed under EPA Rules, 1989 viz. 75 dBA (day time) and 70 dBA (night time).	It has been found that PAs are conducting monitoring of noise and noise level is within the prescribed limit.
v.	The project authorities must strictly comply with the provisions made in Manufacture, Storage and Import of Hazardous Chemicals Rules 1989 as amended in 2000 for handling of hazardous chemicals etc. Necessary approvals from Chief Controller of Explosives must be obtained before commission of the project	It was stated that the PAs have applied for renewal of authorization for generation, handling, collection, storage and disposal of hazardous waste from SPCB, Odisha.
vi.	The project authorities must strictly comply with the rules and regulations with regard to handling and disposal of hazardous wastes in accordance with the Hazardous Wastes (Management and Handling) Rules, 2003. Authorization from the State Pollution Control Board must be obtained for collections/treatment/storage/disposal of hazardous wastes.	The PAs have obtained renewal of Authorization vide letter No.IND-IV-HW-930/9936 dated 27.07.2017, which is valid up to 31.03.2019. As submitted in Form 3 of Hazardous and other Wastes, PAs have stored FCC spent catalyst 738.15 MT in 2016-17. However, in 2017-18 they have stored 121.0 MT at the end of December, 2017 which is found well below the limit prescribed in the authorization certificate.

( ) [50] ( ) [5] ( ) [6] ( ) [6] ( ) [6] ( ) [7] ( )

(डा. ए. के. गुप्ता)
(DR. pA. K. GUPTA)
संयुक्त निदेशके/JOINT DIRECT
भारत सरकार/ Govt. of Ind
पर्यावरण वन एवं ज.प. मंत्रालय/ Min. of Env पूर्वी क्षेत्रीय कार्यालय/ Eastern Regio भुवनेश्वर/ Bhubaneswar-751023

(झ. ए. के. गुप्रा

Ministry's EC No. J-11011/70/2007-1A II (I) dated July 6, 2007

Public Liability Insurance (PLI)

. Oli in i diggia 1996 Angre gage 2017 an an inagre gage 2017 an angre angré a 1997 an angrésaga 1998 an angrésaga (डा. ए. के. गुप्ता) (DR. A. K. GUPTA) संयुक्त निदेशक/JOINT DIRECTOR भारत सरकार/ Govt. of India गर्यावरण वन एवं ज.प. मंत्रालय/Min. of Env. Fore रूवी क्षेत्रीय कार्यालय/Eastern Regional G

(डा० ए० के० गुप्ता)

संयुक्त निदेशक "वै०"

भुवनेश्वर/ Bhubaneswar-751023

The PAs have obtained PLI from the New India

Assurance Co. Ltd. on 11.04.2017.