

SITE INSPECTION NOTE OF VISIT OF SEAC SUB-COMMITTEE TO THE PROPOSED MINING SITE OF SH. THAKUR DASS, S/O SH. UTTAM CHAND & SH. BHISHM KUMAR, S/O SH. DEVINDER NATH, M/S BALA TIKKA ASSOCIATION, VILLAGE-SAKOHAR, P.O. MOVI SERI, TEHSIL-CHACHYOT, DISTRICT-MANDI, H.P.

The site proposed for mining by **Sh. Thakur Dass** was visited by the **Sub Committee of SEAC** in the fore-noon of **02.07.2021**. The site as per the Revenue Records measures about 7-00-00 Bighas, 0.57 ha, Private land hill slope. The committee comprised of the following:

1. Sh. Kulraj Kapoor, Member SEAC
- 2 Dr. Suresh C. Attri, PSO (Env.), DEST

The following representatives along with Govt. officials were also present during the site visit,

- 1 Sh. Thakur Dass, Owner.
- 2 Sh. Hira Singh.
- 3 Sh. Dolam Singh Negi, Patwari, Chachyot.
- 4 Sh. Manish Kumar, Patwari Sahyak.


At the very beginning, the Sub Committee verified the location, situation, orientation, form, physical features / entities both, natural and manmade as well as spatial extent of proposed mining site with reference to the details given in the project report submitted by the proponent for appraisal by the SEAC and found everything in order. It is further confirmed on site that it is a hill slope mining project on private land.

The mining lease area is having variable slope angles. The hill slope of the part of site is reasonably gentle and becomes steep to the extent of about 45° towards ridge of the hill.

This case was exhaustively deliberated in 77th & 78th meetings of SEAC. where it was observed that keeping in view the site condition it is important to undertake a visit of site w.r.t. site conditions.


After checking the compliance the sub-committee observed that:-


- a) The gradient of road shown in geological plans / maps is as per the actual condition of site and it seems to be feasible. The boundary pillars were found at the site. The project proponent need to be directed to carry out mining as per approved mining plan.


2/7

- b) The sub-committee observed that a the Electric pole of single phase line is nearby located but not in the mining site. The project proponent need to give an undertaking for not to disturb it or damage it during mining activities.
- c) The sub-committee observed that the project proponent will start mining operational as per method of mining envisaged under mining plan.
- d) The mining site is accessible by road.

In view of the above, and other relevant issues discussed on the site with the proponent concerned Patwaris and the Panchayat Presidents, the Sub-committee recommends the proposal of Sh. Thakur Dass for further consideration and technical appraisal by the SEAC accordingly.


Dr. S.C. Attri
PSO(Env.), DEST


Sh. Kulraj Kapoor,
Member, SEAC

Date: 02.07.2021

SITE PHOTOGRAPHS

